

## Using proofSIGN with Best Colorproof / Best Screenproof RIP

1. Copy the file 'proofSIGN Chart.tif' from the proofSIGN CD into the following folder:-

C:\Program Files\BestColoproof\ControlStrip

*If you have installed the Best RIP into a different location you will need to amend the location accordingly.*

2. To activate your new proofSIGN strip

a) Restart the RIP

b) From the main Queue screen, Right click on the Queue you will be using to verify your files, then select 'Job settings' (example below)

**Job settings**

Queue  
Olmecc260satin

Color Management | Spot colors | Format / adaptation | **Output** | Special

Job parameters

☒ will be printed Settings

☐ Print Ink Key Assistance  
Number of zones: 8

Print

☒ Print during calculation

☐ No. of copies: 1

☐ Sort output

Printer options

Enter special features of your printer here. Please be aware that not all printers have special features. Settings

Color separations


☐ Print color separations for separate jobs Settings

OK Cancel Apply Help

c) Select the 'Output' Tab, then under Job Parameters tick the 'will be printed' box and click the 'Settings' button.

d) From the 'Job Ticket Settings' tab, select the information you wish to include from the left hand tick boxes, tick the 'Printing control strip' and 'Print control strip

with color management' boxes at the bottom and browse to and select the 'proofSIGN chart.tif' in the browse option.



The image shows a 'Job ticket settings...' dialog box with a blue title bar containing a question mark and a close button. The dialog is divided into several sections. The first section, 'Job ticket contains', has a list of checkboxes: 'Document name', 'File names', 'Date & Time of Job', 'ICC profile names', 'Linearization', 'Rendering intent', 'Resolution', 'Scaling', 'Queue', and 'Job type'. To the right of this list are three buttons: 'OK', 'Cancel', and 'Help'. The second section, 'Printing method', has a text box containing 'Bodoni Systems Calibrated'. The third section, 'Control strip', has a checkbox for 'Printing control strip' which is checked. Below this is a text box containing 'proofSIGN Chart.tif' with a browse button (a folder icon) to its right. At the bottom, there is a checkbox for 'Print control strip with color management' which is also checked.

**Job ticket settings...**

Job ticket contains

- ☒ Document name
- ☒ File names
- ☒ Date & Time of Job
- ☒ ICC profile names
- ☒ Linearization
- ☐ Rendering intent
- ☒ Resolution
- ☒ Scaling
- ☐ Queue
- ☐ Job type

Printing method

Bodoni Systems Calibrated

Control strip

- ☒ Printing control strip

proofSIGN Chart.tif

- ☒ Print control strip with color management

OK Cancel Help